PURCHASE ORDER

Philippine Ports Authority

Run Date: 04-OCT-2023 14.27 40
Run By: BUITIZONRC

Supplier: SHAW AUTOMOTIVE RESOURCES, INC
Address: Diversion Road Balagtas
TIN: 220-842-358-003
PO Type: STANDARD

PO No.: BAT-1744-23
PO Date: 29-SEP-23
PR No.: BAT-1375-23
PR Date: 17-JUL-23

Mode of Procurement: DIRECT

Gentlemen:
Please furnish this Office the following articles subject to the terms and conditions contained herein:

Place of Delivery: PMO - BAT

Delivery Term: 90 days upon receipt of Notice or Purchase Order

Date of Delivery:

Payment Term: Immediate

Item No.	Unit	Description	Quantity	Unit Cost	Amount
OOS-ASD1067	PC	Miscellaneous (Cleaning and Reprocessing of Air-Conditioning Unit)	1.00	267.8571	267.86
OOS-ASD1067	PC	Parts Cleaner (Under Chassis Repair)	1.00	274.1071	274.11
OOS-ASD1067	PC	Miscellaneous (Under Chassis Repair)	1.00	267.8571	267.86
OVP-ASD515	PC	Tie Rod LH/RH (Under Chassis Repair)	1.00	3,303.5714	3,303.57
OVP-ASD524	PCS	Compressor Oil (Cleaning and Reprocessing of Air-Conditioning Unit)	1.00	491.0714	491.07
OVP-ASD544	PC	Front Stabilizer Link LH/RH (Under Chassis Repair)	1.00	3,750.0000	3,750.00
OVP-ASD544	LOT	Front Stabilizer Link LH/RH (Under Chassis Repair) Labor	1.00	2,232.1429	2,232.14
OVP-ASD544	PC	Front Stabilizer Bushing LH/RH (Under Chassis Repair)	1.00	803.5714	803.57
OOS-ASD1271	PC	Freon (Cleaning and Reprocessing of Air-Conditioning Unit)	1.00	2,142.8571	2,142.86
OVP-ASD712	PC	O-Ring (Cleaning and Reprocessing of Air-Conditioning Unit)	1.00	312.5000	312.50
CSP-ASD039	PC	Parts Cleaner (Repair of Engine Accessory)	1.00	274.1071	274.11
DGT-PPA1405	PC	Rack End LH/RH (Under Chassis Repair)	1.00	3,214.2857	3,214.29
DGT-PPA1405	LOT	Rack End LH/RH (Under Chassis Repair) Labor	1.00	3,125.0000	3,125.00
DGT-PPA1405	PC	Front Shock Absorber LH/RH (Under Chassis Repair)	1.00	14,107.1429	14,107.14
DGT-PPA1405	LOT	Front Shock Absorber LH/RH (Under Chassis Repair) Labor	1.00	1,339.2857	1,339.29
DGT-PPA1405	PC	RR Shock Absorber LH/RH (Under Chassis Repair)	1.00	9,732.1429	9,732.14
DGT-PPA1405	LOT	RR Shock Absorber LH/RH (Under Chassis Repair) Labor	1.00	1,339.2857	1,339.29
DGT-PPA532	PC	Aircon Filter (100,000 km Check-up)	1.00	1,354.4643	1,354.46
OOS-ASD1067	PC	Miscellaneous (100,000 km Check-up)	1.00	267.8571	267.86
OSE-ASD764	LOT	Complete Wash (100,000 km Check-up)	1.00	892.8571	892.86
ORMEASD790	LOT	EGR Cleaning (Repair of Engine Accessory) Labor	1.00	4,017.8571	4,017.86
ORMEASD790	PC	Thermistor (Cleaning and Reprocessing of Air-Conditioning Unit)	1.00	2,107.1429	2,107.14
ODS-ASD331	PC	Silica Gel (Cleaning and	1.00	687.5000	687.50

PURCHASE ORDER

Philippine Ports Authority

Run Date: 04-OCT-2023 14:27:40
Run By: BUITIZONRC

Supplier: SHAW AUTOMOTIVE RESOURCES, INC
Address: Diversion Road Balagtas
TIN: 220-842-358-003
PO Type: STANDARD

PO No.: BAT-1744-23
PO Date: 29-SEP-23
PR No.: BAT-1375-23
PR Date: 17-JUL-23

Mode of Procurement: DIRECT

Gentlemen:
Please furnish this Office the following articles subject to the terms and conditions contained herein.

Place of Delivery: PMO - BAT

Delivery Term: 90 days upon receipt of Notice or Purchase Order

Date of Delivery:

Payment Term: Immediate

Item No.	Unit	Description	Quantity	Unit Cost	Amount
		Unit)			
ODS-ASD331	PC	Silica Gel Cap (Cleaning and Reprocessing of Air-Conditioning Unit)	1.00	616.0714	616.07
OOS-ASD3343	PC	Alternator Pulley (Repair of Engine Accessory)	1.00	5,975.8929	5,975.89
OOS-ASD3343	LOT	Alternator Pulley (Repair of Engine Accessory) Labor	1.00	3,125.0000	3,125.00
BAT-AS0035	PC	Differential Oil (100,000 km Check-up)	1.00	937.5000	937.50
BAT-AS0038	PC	Fuel Filter (100,000 km Check-up)	1.00	1,334.8214	1,334.82
BAT-AS0038	PC	Fuel Sensor (100,000 km Check-up)	1.00	1,623.2143	1,623.21
OTV-ASD007	PCS	Brake Fluid (100,000 km Check-up)	1.00	500.0000	500.00
ILOFCMD01	PC	Engine Treatment (100,000 km Check-up)	1.00	919.6429	919.64
NPS-PPA1530	PCS	ATF (100,000 km Check-up)	1.00	3,504.4643	3,504.46
OVP-ASD345	PC	Expansion Valve Front (Cleaning and Reprocessing of Air-Conditioning Unit)	1.00	4,012.5000	4,012.50
OVP-ASD345	LOT	Expansion Valve Front (Cleaning and Reprocessing of Air-conditioning Unit) Labor	1.00	6,696.4200	6,696.42
OVP-ASD345	PC	Expansion Valve Rear (Cleaning and Reprocessing of Air-Conditioning Unit)	1.00	4,160.7143	4,160.71
NPS-PPA1677	PC	Idler (Repair of Engine Accessory)	1.00	16,682.1429	16,682.14
DGT-SVC021	PC	Lower Arm LH/RH (Under Chassis Repair)	1.00	15,892.8571	15,892.86
DGT-SVC021	LOT	Lower Arm LH/RH (Under Chassis Repair) Labor	1.00	2,232.1429	2,232.14
DAV-SUP201	PC	Coolant (100,000 km Check-up)	1.00	1,071.4286	1,071.43
OTV-ASD011	PC	Engine Flushing (100,000 km Check-up)	1.00	1,160.7143	1,160.71
OVP-ASD460	PC	Brake Cleaner (100,000 km Check-up)	1.00	766.9643	766.96
NPS-PPA2472	PC	Auto Tensioner (Repair of Engine Accessory)	1.00	3,964.2857	3,964.29
DGT-PPA532	PC	Air Filter (100,000 km Check-up)	1.00	813.3929	813.39
OVP-ASD297	PC	Serpentine Belt (100,000 km Check-up)	1.00	2,350.5000	2,350.50
BAT-AS0035	PC	Engine Oil Filter (100,000 km Check-up)	1.00	589.2857	589.29
BAT-AS0035	LOT	Engine Oil Filter (100,000 km Check-up) Labor	1.00	3,410.0000	3,410.00
BAT-AS0035	PC	Motor Oil FS (100,000 km Check-up)	1.00	5,000.0000	5,000.00
OOS-ASD1067	PC	Miscellaneous (Repair of Engine	1.00	267.8571	267.86

PURCHASE ORDER

Philippine Ports Authority

Run Date: 04-OCT-2023 14:27:40
Run By: BUITIZONRC

Supplier: SHAW AUTOMOTIVE RESOURCES, INC
Address: Diversion Road Balagtas
TIN: 220-842-358-003
PO Type: STANDARD

Mode of Procurement: DIRECT

PO No.: BAT-1744-23
PO Date: 29-SEP-23
PR No.: BAT-1375-23
PR Date: 17-JUL-23

Gentlemen:
Please furnish this Office the following articles subject to the terms and conditions contained herein:

Place of Delivery: PMO - BAT

Date of Delivery:

Delivery Term: 90 days upon receipt of Notice or Purchase Order

Payment Term: Immediate

INPUT VAT 12	17,269.48
Total: One Hundred Sixty-One Thousand One Hundred Eighty-One & 75/100 Pesos	161,181.75

In case of failure to make the full delivery within the time specified above, a penalty of one-tenth (1/10) of one percent of the total value of this Order for each day of delay shall be imposed.

It is understood that this Purchase Order will be served in Accordance with applicable laws, rules and regulations.

Recommending Approval:

Margarita Emelyn B. Villamor
Division Manager A, Administrative Division

Approved:

Joselito O. Sinocruz
Port Manager

Conforme:

Signature Over Printed Name of Supplier

Date 10/10/23

Funds Available:

Raquel B. Lacsamana
Corporate Finance Services Chief

BAGONG PILIPINAS

PHILIPPINE PORTS AUTHORITY

1 0052308

OCT 05 2023

CARLITO AMACATO
Service Manager
Shaw Automotive Resources Inc.
Hyundai Batangas City
Diversion Road, Balagtas, Batangas City
hyundaibatangascity.0205@gmail.com

Dear **Mr Amacato:**

As part of the globalization of services being offered in the Philippine Ports Authority – Port Management Office of Batangas (PPA-PMO BGS), international set of standards have been adopted in our operations following conformance to the Integrated Management System (IMS), namely:

- Environmental Management System: ISO 14001:2015
- Occupational Health and Safety Management: ISO 45001:2018
- Quality Management System: ISO 9001:2018

In this regard and as part of the Interested Parties doing business with us, we would like to inform you that as our legitimate supplier, you are hereby advised to abide, through all possible means, our established EHSQ Policy as stated below:

> *It is the policy of PPA to establish and implement and Integrated Management System which aims to:*
>
> - *Reduce environmental impact form port activities*
> - *Protect the well-being of all interested parties; and*
> - *Continually improve the quality of port operations and services.*

Thank you very much and we highly expect your cooperation on the matter.

Truly yours,

JOSELITO O SINGCRUZ PhD
Port Manager

ADMIN:MEBV/RCB/smgm