



Republika ng Pilipinas  
PANGASIWAAN NG DAUNGAN NG PILIPINAS  
(PHILIPPINE PORTS AUTHORITY)  
Marsman Bldg South Harbor, Port Area  
Manila, Philippines

TELEPHONE NOS 47 92 04  
40-81-66  
48 24 93

November 3, 1989

PPA MEMORANDUM CIRCULAR  
NO. 37 89

T O : All Port District Managers, Port Management  
Office Managers, Shipping Companies, Pilots'  
Associations and Others Concerned

S U B J E C T : Addendum to PPA Memorandum Circular No. 26-89  
"Establishment/Designation of Pilots' Boarding  
Stations Nationwide"

In addition to the list of Pilots' Boarding Stations designated  
under PPA Memorandum Circular No. 26-89, the following coordinates  
shall be the established pilots' boarding station for the Port of  
Bataan:

In between Corregidor Island and Lucanin Point  
(Approximately: Lat.  $14^{\circ} 26.5' N$   
Long.  $120^{\circ} 30.0' E$ )

For compliance.

  
ROGELIO A. DAYAN  
General Manager