




REPUBLIKA NG PILIPINAS
PANGASIWAAN NG DAUNGAN NG PILIPINAS
PHILIPPINE PORTS AUTHORITY



FEB 03 2000

PPA MEMORANDUM CIRCULAR
NO. 06 - 2000

TO . All District Managers, Port Managers,
Shipping Companies, Pilots' Associations
All Others Concerned

SUBJECT . REVISED PILOTS' BOARDING STATION (PBS) AND
ANCHORAGE GROUNDS AT THE TERMINAL PORT
OF BACOLOD, PMO - PULUPANDAN

The designated anchorage grounds and Pilots' Boarding Station (PBS) at the Terminal Port of Bacolod, PMO-Pulupandan, as established in PPA Memorandum Circular No. 50-99 dated November 10, 1999, are hereby amended in order to preclude damages to underwater cables as-laid in the area.

Accordingly, the Pilots' Boarding Station and Anchorage Area (B) of said port shall be as follows:

Pilots' Boarding Station (PBS)

Latitude 10° 41.5' North - Longitude 122° 53.8' East

Anchorage Area (B)

A. Latitude 10° 40 5' North - Longitude 122° 54 6' East

B. Latitude 10° 40 5' North - Longitude 122° 51 3' East

C. Latitude 10° 37 9' North - Longitude 122° 51 3' East

D. Latitude 10° 37 9' North - Longitude 122° 52.4' East

The coordinates of Anchorage Area (A) shall remain as is

All other provisions of PPA MC No 50-99 shall be observed/complied with by all concerned

Copies of this revised order shall be furnished the following.

- a. Commandant, Philippine Coast Guard**
- b. Director, Coast & Geodetic Survey, NAMRIA**
- c. President, Domestic Shipowners Association**
- d. President, Philippine Interisland Shipping Association**
- e. President, Association of International Shipping Lines**
- f. President, United Harbor Pilots' Association of the Phils.**
- g. Chief Pilot, Pulupandan Pilotage Association**

This Order shall take effect immediately.



JUAN O PENA

General Manager

**Attached Portion of Chart No 4416 "Iloilo and Guimaras Strait"
indicating the Pilots' Boarding Station and Anchorage Area B**

