

SUPPLY, DELIVERY, INSTALLATION AND COMMISSION OF ENVIRONMENT MONITORING SYSTEM FOR PPA HEAD OFFICE DATA CENTER

In compliance with the QMS pre-audit findings.

Monitoring System:

- Temperature & Humidity Sensor Equipment/Devices (Units to be installed should be able to cover the whole data center)
- Certification of Calibration for Sensor Equipment Devices is required from the Principal

Display/Output:


- Monitor (32") – output of Sensor Equipment/Devices should be displayed in monitor
- Work Station – should be remotely accessible

Materials

- All necessary materials and accessories to install the Temperature & Humidity Sensor Equipment/Devices and Display Monitor

Scope of Supply and Works:

- Supply and installation of temperature and humidity sensor equipment.
- Supply and installation of work station unit and accessories.
- Supply and installation of monitoring display with mounting brackets.
- Supply of installation and wiring materials.
- Supply of roughing-in materials.
- Supply of brackets and installation kits.
- Cable and wiring termination.
- Testing of all supplied equipment.
- Commissioning of the entire system.
- Turn-over and Acceptance.


GERVACIO ALFREDO N. BALATBAT
Division Manager – ICTD, ORSD